

FIG.1

RESIDUAL OXIDE FILM OR RESIST CANNOT BE CONFIRMED FROM SAMPLE SURFACE








FIG.4








FIG.5



DEFECT










FIG.10




FIG.11




FIG.12

